

ATKA AIRPORT

Contents:

- A Pavement Strength Form showing project history, latest Pavement Condition Index (PCI) data, pavement strength ratings (if available) and other useful information
- A Pavement Condition Survey – PCI Sample Unit Layout Plan
- PCI maps showing as-measured and predicted pavement conditions
- Age map showing pavement age as of January 2002
- A Branch PCI Condition Report
- A Section PCI Condition Report

Airport Information:

- Location: On Atka Island, is near the mid point of the Aleutian Island chain at approximately Longitude 174° West and Latitude 52° North.
- District: Southwest
- Airport Manager: Troy Larue oversees contract maintenance
- District Maintenance Manager: Andy Peterson
- Pavement Surface: Slurry Seal over Asphalt Concrete
- Last Pavement Construction: Slurry Seal in 1989
- Pavement layout: Runway 15-33, Taxiway A and Apron
- Design Aircraft: DC-3
- 2001 Enplanements: 0 (reported)
- Airport Class: Non-Primary
- Last pavement condition survey: August 1999
- Next planned pavement condition survey: 2003 or 2004
- 2002 reported pavement maintenance and/or changed conditions: Rehabilitation design in progress
- Recommendations: See PCI maps